

# Tilkoblingsanvisning for sokkel type BWA-40A/1

Figurene viser en av flere måter å føre kabelen inn i sokkelen på. For åpent opplegg finnes 8 svekninger hvor kabelen kan føres inn / ut.


Ved montering på veggboks føres kabelen inn via åpninger langs kanten av sokkelen.

**NB! Sørg for at samtlige skruer er godt tildratt.**

Sokkelen skal monteres på plant underlag. Detektorens innebygde alarmindikator bør vende mot døråpningen. Pilen merket LED viser hvilken retning den innebygde alarmindikatoren er best synlig.

Standard festehullsavstand er 60 mm. Benytt skru DIN 96-3,5XL-ST. - Ved alternativ festehullsavstand : (35 mm - 50 mm), benytt skru DIN 96-4,5XL-ST.

Vær oppmerksom på at total sløyfemotstand ikke må overstige  $30\Omega$ , dvs.  $15\Omega$  i hver leder.



# Connections for socket type BWA-40A/1

The figures below show 3 methods of connecting the cables into the socket. There are 8 cut-outs around the circumference available for cable entry. When flush mounting the cables may enter the socket via these cut-outs.

**Note! Ensure that all terminal screws are tightened firmly.**

The socket must be mounted to a flat surface. The internal alarm LED of the detector should face the entrance door. Arrow marked LED in Fig. 1 and 4 shows the direction from where the alarm LED is visible.

There are 2 fixing positions available:  
 1 - Fixed 60mm centres (M3,5max)  
 2 - Adjustable from 35-50mm (M4 max).

The total resistance of the detector loop must not exceed  $30\Omega$ , that is  $15\Omega$  in each conductor.

